



Gap Solution for Excessive Fire Door Bottom Undercut/Clearance — 45 Minute

UL Certified Solutions for Fire doors with Excessive Door Bottom Clearance up to 1-1/2"

NGP-Edge® Intumescent Door Shoes



9245 Series

UL Certified Miscellaneous Fire Door Accessory for excessive door bottom undercut/clearance, measuring up to 1-1/2"

45 minute rated UL10B and UL10C wood or hollow metal fire doors

Restricts the passage of smoke

End caps available - sold separately




Gasketing options:

- 9245NWA** neoprene & nylon brush
- 9245NWDKB** neoprene & nylon brush

#6 x 3/4" Stainless Steel SMS furnished.

A- anodized aluminum
DKB - dark bronze


vinyl is gray
neoprene is black
thermoplastic is dark brown
nylon brush is gray with anodized aluminum; black with DKB metal




neoprene




nylon brush



vinyl



thermoplastic



nylon brush & thermoplastic

