





# Gap Solution for Excessive Fire Door Bottom Undercut/Clearance — 90 Minute

UL Certified Solutions for Fire doors with Excessive Door Bottom Clearance up to 1-1/2"

## NGP-Edge® Intumescent Door Shoe

### 9590

UL Certified Miscellaneous Fire Door Accessory for excessive door bottom undercut/clearance, measuring up to 1-1/2"

90 minute rated UL10B and UL10C wood or hollow metal fire doors

Restricts the passage of smoke

Non-Handed

Brushed stainless steel  
neoprene is black

Patent Pending

#### Product consists of:

- #304 Brushed Stainless Steel Neoprene Sweep - pull side
- #304 Brushed Stainless Steel Intumescent Shoe - push side
- #304 Brushed Stainless Steel End Caps

Available in 36", 48" lengths

#6 x 3/4" Stainless Steel SMS furnished

